Auto Fix Pre Inspection Vehicle Check



Sheet Nullibrand Car Service							
ate : 04-01-2121		Make : Lam	borghi	ni	Model : Aventador		
Veh Reg No- : 456		Color :			Mileage : 45000		
Start Time : 01:03 pm			Finish Time :				
Check Point	Condition			Check Poi	nt .	Condition	
	Ok	Not Ok	- Officer of officer		T.	Ok	Not Ok
Cluster Meter Warning			Tire Condition				
Seat Belt Operation			Front Suspension Bushed				
Lighting- Interior & Exterior			Shoo	ock Absorber			
Wiper Blade				Prive Shaft Boot & Propoller Shaft			
Fuel Filling Cap			Engi	ne Mounting			
AC Cooling			Drive	e Belt Condition			
Power steering Fluid				Driver belt Tensioner			
AC Filter Condition			Fron	Front Brake Pad			
Air Filter Condition			Fron	Front Brake Disc			
Clutch Fluid & pedal play			Rea	lear Brake Pad/Shoe			
Stereo Operation			Rear Brake Disc/Drum				
Hand Brake Operation			Engi	ne Oil Level			
Door Hinges			Engine Cooling Fan				
Coolant Level			Unde	erCarriage Corrison			
Additional Remarks:							
rt				yry			
rty				yrtytry			
Pre Road Test Remarks:							
rtyrt							
rtrty							