Auto Fix Pre Inspection Vehicle Check Sheet



| Sneet Nullibrand Conservice | | | | | | | |
|-------------------------------|-----------|-----------------|-------------------------|------------------------|------------------------|-----------|--|
| Date : 14-01-2121 | | Make : Nissa | an | Model : Altima | Model : Altima | | |
| Veh Reg No- : b | | Color : | | Mileage : 72436 | Mileage : 72436 | | |
| Start Time : 11:58 am | | | Finish Time : | Finish Time : | | | |
| Check Point | Condition | | Check I | Point | Con | Condition | |
| | Ok | Not Ok | | | Ok | Not Ok | |
| Cluster Meter Warning | | | Tire Condition | | | | |
| Seat Belt Operation | | | Front Suspension Bushed | | | | |
| Lighting- Interior & Exterior | | | Shock Absorber | | | | |
| Wiper Blade | | | Drive Shaft Boot & Prop | | | | |
| Fuel Filling Cap | | | Engine Mounting | | | | |
| AC Cooling | | | Drive Belt Condition | | | | |
| Power steering Fluid | | | Driver belt Tensioner | | | | |
| AC Filter Condition | | Front Brake Pad | | | | | |
| Air Filter Condition | | | Front Brake Disc | | | | |
| Clutch Fluid & pedal play | Re | | Rear Brake Pad/Shoe | Rear Brake Pad/Shoe | | | |
| Stereo Operation | | | Rear Brake Disc/Drum | | | | |
| Hand Brake Operation | | | Engine Oil Level | | | | |
| Door Hinges | | | Engine Cooling Fan | | | | |
| Coolant Level | | | UnderCarriage Corrison | | | | |
| Additional Remarks: | | | | | | | |
| Tyresvneeds to replace | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Pre Road Test Remarks: | | | | | | | |
| Noise from wheel bearing | | | | | | | |
| | | | | | | | |